

PROSPECTOR™

The Gold Standard In Toolmaking

PowerSource Insight Changes Not Appearing to Go Into Effect

The information in this tip applies to:

- Prospector (all versions)

ISSUE

Changes have been made to the databases through PowerSource Insight, however the changes do not seem to be going into effect inside Prospector.

SUGGESTION

Make sure you are making changes in PowerSource Insight for the corresponding units (inches or millimeters) that match the Prospector projects you are working with. See the following diagram.

