

PROSPECTOR™


The Gold Standard In Toolmaking

A Quick Way to Select Points (by Using Strokes)

The information in this tip applies to:

- Prospector (all versions)
-


SUMMARY

Rather than clicking on the point select button () to select points, you can save time by using a top-right to bottom-left stroke with the mouse. You can use this stroke to select points on profiles or cutter path (selecting points on a profile applies to version 6.0 and above).


MORE INFORMATION

See the following diagrams on how to carry out this stroke.


Let's say we have the following profile, and we would like to select the point on one of its corners:



Do a top-right to bottom-left stroke with the mouse to select the point on this corner:



The point in this corner will be selected, and the result will look like the following:



Note: You can unselect points by doing the opposite stroke, bottom-left to top-right.

